



## **Fermo VIS**

Manual positioning



Stop gauge system with profile support, positioning of the stop via handwheel and reading of position on the digital readout.



### **VIS digital reader**

Digital display that allows reprogramming of machine 0, indicating the stop positioning dimension, which corresponds to the length of the workpiece to be cut.



### **Handwheel**

By means of the handwheel, the stop is brought into position.



### **Reference stop**

Carriage running on ball bushing actuated by mechanically controlled kinematics, which allows, referring to the centre of the blade, the realization of the length of the workpiece to be cut.

